

Field ID	Type	Location	Flushed Y/N	y Sample ID	y Name	Certificati on ID	Date Sampled	Time Sampled	Analytical Method	Date of Analysis	Time of Analysis	Concentration Limit in ug/L (ug/L)	Dilution Factor	Digested (Y/N)	Qualifier
FB-FIELD BLANK			N	3-0001	EMSL	03036	12/19/2016	04:06	200.8	12/29/2016	21:26	<1.00 1.00		1 N	
1-BES-1-KITCHEN-KS1-1	Sink	Kitchen	N	3-0002	EMSL	03036	12/19/2016	04:08	200.8	12/29/2016	21:28	14.9 1.00		1 N	
2-BES-2-KITCHEN-KS2-1	Sink	Kitchen	N	3-0003	EMSL	03036	12/19/2016	04:10	200.8	12/29/2016	21:29	<1.00 1.00		1 N	
3-BES-29-KITCHEN-KS9-1	Sink	Kitchen	N	3-0004	EMSL	03036	12/19/2016	04:12	200.8	12/29/2016	21:30	<1.00 1.00		1 N	
5-BES-4-HOME EC-KS4-1	Sink	Home Ec	N	3-0006	EMSL	03036	12/19/2016	04:23	200.8	12/29/2016	21:31	2.76 1.00		1 N	
6-BES-5-HOME EC-KS5-1	Sink	Home Ec	N	3-0007	EMSL	03036	12/19/2016	04:25	200.8	12/29/2016	21:32	2.50 1.00		1 N	
8-BES-7-HOME EC-KS7-1	Sink	Home Ec	N	3-0009	EMSL	03036	12/19/2016	04:29	200.8	12/29/2016	21:34	11.8 1.00		1 N	
11-BES-10-CLASS-CS2-1	Sink	Classroom	N	3-0012	EMSL	03036	12/19/2016	04:36	200.8	12/29/2016	21:36	2.48 1.00		1 N	
12-BES-14-GIRLS-TS3-1	Sink	Restroom	N	3-0013	EMSL	03036	12/19/2016	04:40	200.8	12/29/2016	21:38	6.49 1.00		1 N	
13-BES-15-GIRLS-TS4-1	Sink	Restroom	N	3-0014	EMSL	03036	12/19/2016	04:42	200.8	12/29/2016	21:39	8.72 1.00		1 N	
14-BES-16-GIRLS-TS5-1	Sink	Restroom	N	3-0015	EMSL	03036	12/19/2016	04:44	200.8	12/29/2016	21:39	13.6 1.00		1 N	
15-BES-17-TOILET-TS6-1	Sink	Restoom	N	3-0016	EMSL	03036	12/19/2016	04:46	200.8	12/29/2016	21:40	<1.00 1.00		1 N	
16-BES-18-TOILET-TS7-1	Sink	Restoom	N	01160876	EMSL	03036	12/19/2016	04:48	200.8	12/29/2016	21:42	3.90 1.00		1 N	
18-BES-21-BOYS-TS8-1	Sink	Restoom	N	3-0019	EMSL	03036	12/19/2016	04:55	200.8	12/29/2016	21:44	4.77 1.00		1 N	
19-BES-22-BOYS-TS9-1	Sink	Restoom	N	3-0020	EMSL	03036	12/19/2016	04:57	200.8	12/29/2016	21:44	2.19 1.00		1 N	
20-BES-23-BOYS-TS10-1	Sink	Restoom	N	3-0021	EMSL	03036	12/19/2016	04:59	200.8	12/29/2016	21:45	6.36 1.00		1 N	
22-BES-25-GIRLS-TS12-1	Sink	Restroom	N	3-0023	EMSL	03036	12/19/2016	05:04	200.8	12/29/2016	22:13	13.9 1.00		1 N	
23-BES-26-GIRLS-TS13-1	Sink	Restroom	N	3-0024	EMSL	03036	12/19/2016	05:07	200.8	12/29/2016	22:14	6.66 1.00		1 N	
4-BES-3-HOME EC-KS3-1	Sink	Kitchen	N	3-0005	EMSL	03036	12/19/2016	04:21	200.8	12/29/2016	21:30	59.6 1.00		1 N	
7-BES-6-HOME EC-KS6-1	Sink	Kitchen	N	3-0008	EMSL	03036	12/19/2016	04:27	200.8	12/29/2016	21:34	25.0 1.00		1 N	
9-BES-8-HOME EC-KS8-1	Sink	Kitchen	N	3-0010	EMSL	03036	12/19/2016	04:31	200.8	12/29/2016	21:35	23.8 1.00		1 N	
10-BES-9-CLASS-CS1-1	Sink	Classroom	N	3-0011	EMSL	03036	12/19/2016	04:33	200.8	12/30/2016	16:55	607 20.0		20 N	
17-BES-20-CLASS-CS3-1	Sink	Classroom	N	3-0018	EMSL	03036	12/19/2016	04:53	200.8	12/29/2016	21:43	70.4 1.00		1 N	
21-BES-24-GIRLS-TS11-1	Sink	Restroom	N	3-0022	EMSL	03036	12/19/2016	05:02	200.8	12/29/2016	22:09	25.7 1.00		1 N	