

| Field ID | Type | Location | Flushed Y/N | Laboratory Sample ID | Laboratory Name | Lab Certification ID | Date Sampled | Analytical Method | Date of Analysis | Time of Analysis | Concentration in ug/L | Reporting Limit (ug/L) | Dilution Factor | Digested (Y/N) |
|-------------------------------------|-------------------|----------------|-------------|----------------------|-----------------|----------------------|--------------|-------------------|------------------|------------------|-----------------------|------------------------|-----------------|----------------|
| 10-CAMV-91-KITCHEN-KS9-1 | Sink | Kitchen | N | 011608921-0011 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:49 | <1.00 | 1.00 | 1 | N |
| | Drinking Fountain | | | | | | | | | | | | | |
| 10-CAMV-E6-H073-EDF6-1 | Fountain | Corridor | N | 011700615-0011 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:52 | <1.00 | 1 | 1 | N |
| 11-CAMV-79-DRINK FOUNTAIN-GYM-DF5-1 | Drinking Fountain | Corridor | N | 011700615-0012 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:54 | <1.00 | 1 | 1 | N |
| 11-CAMV-92-KITCHEN-IM-1 | Sink | Kitchen | N | 011608921-0012 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 22:21 | <1.00 | 1.49 | 1 | N |
| 12-CAMV-10-KITCHEN-TS1-1 | Sink | Restroom | N | 011608921-0013 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:51 | 1.02 | 1.00 | 1 | N |
| 12-CAMV-80-DRINK FOUNTAIN-GYM-DF6-1 | Drinking Fountain | Corridor | N | 011700615-0013 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:55 | <1.00 | 1 | 1 | N |
| 13-CAMV-11-TOILET-TS2-1 | Sink | Restroom | N | 011608921-0014 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:52 | <1.00 | 1.00 | 1 | N |
| 13-CAMV-81-DRINK FOUNTAIN-GYM-DF7-1 | Drinking Fountain | Corridor | N | 011700615-0014 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:55 | <1.00 | 1 | 1 | N |
| 14-CAMV-12-TOILET-TS3-1 | Sink | Restroom | N | 011608921-0015 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:52 | 1.53 | 1.00 | 1 | N |
| 15-CAMV-13-FACULTY-CS2-1 | Sink | Faculty Lounge | N | 011608921-0016 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:53 | 2.69 | 1.00 | 1 | N |
| 16-CAMV-14-PARENT-CS3-1 | Sink | Parent Lounge | N | 011608921-0017 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:54 | 19.9 | 1.00 | 1 | N |
| 17-CAMV-15-NURSE-CS4-1 | Sink | Nurse's Office | N | 011608921-0018 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:56 | 26.9 | 1.00 | 1 | N |
| 18-CAMV-16-NURSE-CS5-1 | Sink | Nurse's Office | N | 011608921-0019 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 13:43 | 8.04 | 1.00 | 1 | N |
| 19-CAMV-17-NURSE-TS4-1 | Sink | Restroom | N | 011608921-0020 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:57 | 2.03 | 1.00 | 1 | N |
| | Drinking Fountain | | | | | | | | | | | | | |
| 1-CAMV-18-GYM-DF1-1 | Fountain | Corridor | N | 011700615-0002 | EMSL | 03036 | 1/24/2017 | 7/18/1900 | 1/24/2017 | 22:43 | <1.00 | 0:00 | 1 | N |
| 1-CAMV-1-CAFE-CS1-1 | Sink | Cafeteria | N | 011608921-0002 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:37 | 6.67 | 1.00 | 1 | N |
| 20-CAMV-20-MEDIA-CS6-1 | Sink | Media Room | N | 011608921-0021 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:57 | 31.3 | 1.00 | 1 | N |
| 21-CAMV-93-MENS-TS30-1 | Sink | Restroom | N | 011608921-0022 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:59 | 1.24 | 1.00 | 1 | N |
| 22-CAMV-94-MENS-TS31-1 | Sink | Restroom | N | 011608921-0023 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 17:00 | 1.34 | 1.00 | 1 | N |
| 23-CAMV-95-MENS-TS32-1 | Sink | Restroom | N | 011608921-0024 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 17:01 | 1.39 | 1.00 | 1 | N |
| | Womens' | | | | | | | | | | | | | |
| 24-CAMV-96-WOMENS-TS33-1 | Sink | Restroom | N | 011608921-0025 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 17:02 | 1.54 | 1.00 | 1 | N |
| | Womens' | | | | | | | | | | | | | |
| 25-CAMV-97-WOMENS-TS34-1 | Sink | Restroom | N | 011608921-0026 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 17:02 | 1.27 | 1.00 | 1 | N |
| | Womens' | | | | | | | | | | | | | |
| 26-CAMV-98-WOMENS-TS35-1 | Sink | Restroom | N | 011608921-0027 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 17:03 | 1.05 | 1.00 | 1 | N |
| | Lockerroom | | | | | | | | | | | | | |
| 27-CAMV-24-LOCKER-TS5-1 | Sink | Restroom | N | 011608921-0028 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:15 | <1.00 | 1.00 | 1 | N |
| | Lockerroom | | | | | | | | | | | | | |
| 28-CAMV-25-LOCKER-TS6-1 | Sink | Restroom | N | 011608921-0029 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:18 | <1.00 | 1.00 | 1 | N |
| 29-CAMV-28-TOILET-TS8-1 | Sink | Restroom | N | 011608921-0030 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:19 | 1.24 | 1.00 | 1 | N |

| | | | | | | | | | | | | | |
|----------------------------|----------|-----------------|---|----------------|------|-------|------------|-----------|-----------|-------|-------|------|------|
| | Drinking | | | | | | | | | | | | |
| 2-CAMV-19-GYM-DF2-1 | Fountain | Corridor | N | 011700615-0003 | EMSL | 03036 | 1/24/2017 | 7/18/1900 | 1/24/2017 | 22:44 | <1.00 | 0:00 | 1 N |
| 2-CAMV-3-SERV-KS1-1 | Sink | Kitchen | N | 011608921-0003 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:37 | 5.66 | 1.00 | 1 N |
| | | Lockerroom | | | | | | | | | | | |
| 30-CAMV-99-LOCKER-TS8A-1 | Sink | Restroom | N | 011608921-0031 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:20 | <1.00 | 1.00 | 1 N |
| | | Lockerroom | | | | | | | | | | | |
| 31-CAMV-29-LOCKER-TS9-1 | Sink | Restroom | N | 011608921-0032 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:21 | <1.00 | 1.00 | 1 N |
| | | Lockerroom | | | | | | | | | | | |
| 32-CAMV-30-LOCKER-TS10-1 | Sink | Restroom | N | 011608921-0033 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:21 | 1.07 | 1.00 | 1 N |
| 33-CAMV-36-SCIENCE-LS1-1 | Sink | Laboratory | N | 011608921-0034 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:22 | 38.8 | 1.00 | 1 N |
| 34-CAMV-39-SCIENCE-LS2-1 | Sink | Laboratory | N | 011608921-0035 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:23 | 333 | 10.0 | 10 N |
| 35-CAMV-40-SCIENCE-LS3-1 | Sink | Laboratory | N | 011608921-0036 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:23 | 45.5 | 1.00 | 1 N |
| 36-CAMV-38-SP ED-CS7-1 | Sink | Classroom | N | 011608921-0037 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:26 | 2.40 | 1.00 | 1 N |
| | Sink w/ | | | | | | | | | | | | |
| 37-CAMV-100-SP ED-CSB18-1 | Bubbler | Classroom | N | 011608921-0038 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:26 | 3.58 | 1.00 | 1 N |
| 38-CAMV-41-SCIENCE-LS4-1 | Sink | Laboratory | N | 011608921-0039 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:28 | 70.8 | 1.00 | 1 N |
| 39-CAMV-42-SCIENCE-LS5-1 | Sink | Laboratory | N | 011608921-0040 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:29 | 27.0 | 1.00 | 1 N |
| 3-CAMV-4-KITCHEN-KS2-1 | Sink | Kitchen | N | 011608921-0004 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:38 | 4.85 | 1.00 | 1 N |
| | Drinking | | | | | | | | | | | | |
| 3-CAMV-E1-HSU-EDF1-1 | Fountain | Corridor | N | 011700615-0004 | EMSL | 03036 | 1/24/2017 | 7/18/1900 | 1/24/2017 | 22:46 | <1.00 | 0:00 | 1 N |
| 40-CAMV-35-TOILET-TS11-1 | Sink | Restroom | N | 011608921-0041 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:30 | 1.01 | 1.00 | 1 N |
| 41-CAMV-47-BOYS-TS15-1 | Sink | Boys' Restroom | N | 011608921-0042 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:30 | <1.00 | 1.00 | 1 N |
| 42-CAMV-48-BOYS-TS16-1 | Sink | Boys' Restroom | N | 011608921-0043 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:31 | <1.00 | 1.00 | 1 N |
| 43-CAMV-44-GIRLS-TS12-1 | Sink | Girls' Restroom | N | 011608921-0044 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:32 | <1.00 | 1.00 | 1 N |
| 44-CAMV-45-GIRLS-TS13-1 | Sink | Girls' Restroom | N | 011608921-0045 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:35 | <1.00 | 1.00 | 1 N |
| 45-CAMV-50-SCIENCE-LS6-1 | Sink | Laboratory | N | 011608921-0046 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:36 | 28.9 | 1.00 | 1 N |
| 46-CAMV-51-SCIENCE-LS7-1 | Sink | Laboratory | N | 011608921-0047 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 20:37 | 25.0 | 1.00 | 1 N |
| 47-CAMV-101-SCIENCE-LS12-1 | Sink | Laboratory | N | 011608921-0048 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:29 | 24.4 | 1.00 | 1 N |
| 48-CAMV-102-SCIENCE-LS13-1 | Sink | Laboratory | N | 011608921-0049 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:31 | 46.0 | 1.00 | 1 N |
| 49-CAMV-52-CLASS-CS8-1 | Sink | Classroom | N | 011608921-0050 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 22:25 | 92.6 | 1.00 | 1 N |
| 4-CAMV-5-KITCHEN-KS3-1 | Sink | Kitchen | N | 011608921-0005 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:39 | 2.89 | 1.00 | 1 N |
| | Drinking | | | | | | | | | | | | |
| 4-CAMV-E2-HSU-EDF2-1 | Fountain | Corridor | N | 011700615-0005 | EMSL | 03036 | 1/24/2017 | 7/18/1900 | 1/24/2017 | 22:47 | <1.00 | 0:00 | 1 N |
| 50-CAMV-102-CLASS-CSB19-1 | Sink | Classroom | N | 011608921-0051 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:32 | 2.48 | 1.00 | 1 N |
| 51-CAMV-53-ART-CS9-1 | Sink | Classroom | N | 011608921-0052 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:33 | 1.89 | 1.00 | 1 N |
| 52-CAMV-54-ART-CS10-1 | Sink | Classroom | N | 011608921-0053 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:33 | 13.8 | 1.00 | 1 N |
| 53-CAMV-62-BOYS-TS17-1 | Sink | Boys' Restroom | N | 011608921-0054 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:34 | <1.00 | 1.00 | 1 N |
| 54-CAMV-61-BOYS-TS18-1 | Sink | Boys' Restroom | N | 011608921-0055 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:36 | <1.00 | 1.00 | 1 N |

| | | | | | | | | | | | | | | |
|------------------------------------|----------------------|-----------------|---|----------------|------|-------|------------|-----------|-----------|-------|-------|------|---|---|
| 55-CAMV-63-GIRLS-TS21-1 | Sink | Girls' Restroom | N | 011608921-0056 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:37 | <1.00 | 1.00 | 1 | N |
| 56-CAMV-64-GIRLS-TS22-1 | Sink | Girls' Restroom | N | 011608921-0057 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:38 | <1.00 | 1.00 | 1 | N |
| 57-CAMV-68-CLASS-CSB16-1 | Sink w/ Bubbler | Classroom | N | 011608921-0058 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:38 | 1.05 | 1.00 | 1 | N |
| 58-CAMV-69-CLASS-CSB17-1 | Sink w/ Bubbler | Classroom | N | 011608921-0059 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:39 | <1.00 | 1.00 | 1 | N |
| 59-CAMV-104-CLASS-CSB17A-1 | Sink w/ Bubbler | Classroom | N | 011608921-0060 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:41 | <1.00 | 1.00 | 1 | N |
| 5-CAMV-6-KITCHEN-KS4-1 | Sink | Kitchen | N | 011608921-0006 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:44 | 3.44 | 1.00 | 1 | N |
| 5-CAMV-E3-HSU-EDF3-1 | Drinking Fountain | Corridor | N | 011700615-0006 | EMSL | 03036 | 1/24/2017 | 7/18/1900 | 1/24/2017 | 22:49 | <1.00 | 0:00 | 1 | N |
| 60-CAMV-88-SCIENCE-LS11-1 | Sink | Laboratory | N | 011608921-0061 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:42 | 46.6 | 1.00 | 1 | N |
| 61-CAMV-104-SCIENCE-LS14-1 | Sink | Laboratory | N | 011608921-0062 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:42 | 31.0 | 1.00 | 1 | N |
| 62-CAMV-86-SCIENCE-LS10-1 | Sink | Laboratory | N | 011608921-0063 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:44 | 18.4 | 1.00 | 1 | N |
| 63-CAMV-84-SCIENCE-LS9-1 | Sink | Laboratory | N | 011608921-0064 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 22:26 | <1.00 | 1.00 | 1 | N |
| 64-CAMV-83-SCIENCE-LS8-1 | Sink | Laboratory | N | 011608921-0065 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:46 | 47.4 | 1.00 | 1 | N |
| 65-CAMV-82-TOILET-TS29-1 | Sink | Restroom | N | 011608921-0066 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:46 | 1.11 | 1.00 | 1 | N |
| 66-CAMV-77-BOYS-TS28-1 | Sink | Boys' Restroom | N | 011608921-0067 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:47 | <1.00 | 1.00 | 1 | N |
| 67-CAMV-76-BOYS-TS27-1 | Sink | Boys' Restroom | N | 011608921-0068 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:48 | <1.00 | 1.00 | 1 | N |
| 68-CAMV-74-GIRLS-TS25-1 | Sink | Girls' Restroom | N | 011608921-0069 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:01 | <1.00 | 1.00 | 1 | N |
| 69-CAMV-75-GIRLS-TS26-1 | Sink | Girls' Restroom | N | 011608921-0070 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:03 | <1.00 | 1.00 | 1 | N |
| 6-CAMV-66-DRINK FOUNTAIN-GYM-DF3-1 | Drinking Fountain | Corridor | N | 011700615-0007 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:49 | <1.00 | 1 | 1 | N |
| 6-CAMV-7-KITCHEN-KS5-1 | Sink | Kitchen | N | 011608921-0007 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:46 | 1.71 | 1.00 | 1 | N |
| 70-CAMV-73-CLASS-CS18-1 | Sink | Classroom | N | 011608921-0071 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:04 | 6.82 | 1.00 | 1 | N |
| 71-CAMV-105-CLASS-CSB20-1 | Sink w/ Bubbler | Classroom | N | 011608921-0072 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:05 | 2.20 | 1.00 | 1 | N |
| 72-CAMV-71-TOILET-TS23-1 | Sink | Restroom | N | 011608921-0073 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:05 | <1.00 | 1.00 | 1 | N |
| 73-CAMV-72-TOILET-TS24-1 | Sink | Restroom | N | 011608921-0074 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:07 | <1.00 | 1.00 | 1 | N |
| 7-CAMV-67-DRINK FOUNTAIN-GYM-DF4-1 | Drinking Fountain | Corridor | N | 011700615-0008 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:50 | <1.00 | 1 | 1 | N |
| 7-CAMV-8-KITCHEN-KS6-1 | Sink | Kitchen | N | 011608921-0008 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:47 | 1.97 | 1.00 | 1 | N |
| 8-CAMV-9-KITCHEN-KS7-1 | Sink | Kitchen | N | 011608921-0009 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:47 | 6.14 | 1.00 | 1 | N |
| 8-CAMV-E4-H073-EDF4-1 | Drinking Fountain | Corridor | N | 011700615-0009 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:51 | <1.00 | 1 | 1 | N |
| 9-CAMV-90-KITCHEN-KS8-1 | Sink | Kitchen | N | 011608921-0010 | EMSL | 03036 | 12/21/2016 | 200.8 | 1/3/2017 | 16:48 | <1.00 | 1.00 | 1 | N |
| 9-CAMV-E5-H073-EDF5-1 | Drinking Fountain | Corridor | N | 011700615-0010 | EMSL | 03036 | 1/24/2017 | 200.8 | 1/24/2017 | 22:51 | <1.00 | 1 | 1 | N |

FB-FIELD BLANK

N

011608921-0001 EMSL

03036

12/21/2016

200.8

1/3/2017

16:36

<1.00

1.00

1 N